

ZMS00 ZMS01 ZMS02 ZMS03 ZMS04 ZMS05 ZMS06 ZMS07 ZMS08 ZMS09 ZMS10

## SPANNDORNE FÜR SPANNHÜLSEN TYP S


### Zwischenstück für manuelle Betätigung

Art.-Nr.	Ø	P	S
ZMS 00	51,3	23	20
ZMS 01	51,3	23	20
ZMS 02	51,3	23	20
ZMS 03	60,8	28	25
ZMS 04	79,8	28	25
ZMS 05	79,8	28	25
ZMS 06	79,8	40	25
ZMS 07	79,8	40	25
ZMS 08	79,8	40	25
ZMS 09	79,8	42	40
ZMS 10	79,8	42	40



### Spannschraube

Art.-Nr.	H	M	SW
SS 00	75,5	M 6	4
SS 01	80	M 8	4
SS 02	88,5	M 10	6
SS 03	92	M 11 x 1,5	8
SS 04	102	M 12	8
SS 05	102	M 14	8
SS 06	116	M 14	8
SS 07	126	M 14	10
SS 08	136	M 14	10
SS 09	164	M 20	10
SS 10	186	M 20	10



TEL. +43(0)2235 73084

FAX +43(0)2235 73085

was@siftar.com